## CANDU NPP S/W Categorization Methodology for Safety, Plant Control, Monitoring & Testing Systems

This lecture will provide some insight into the categorization methodology that should be taken into consideration for safety critical software for computerized shutdown system applications.

## Lecture topic summary includes:

- Purpose of the S/W Categorization Process
- Necessary Definitions
- Specification of the S/W Categories
- Categorization Process Basis
- Determining Plant System Safety Significance
- Determining S/W Failure Impact Type
- Final S/W Category Determination
- S/W Categorization 1-4 Summary

# Supporting software categorization documents for this lecture that could be consulted for further information:

- COG-95-264 'Guideline for Categorization of Software in Nuclear Power Plant Safety, Control, Monitoring and Testing Systems', 95 September
   22
- CANDU 9 Assessment Document 69-66700-ASD-002, 'Preliminary Categorization of DCS Software'

#### Purpose of the S/W Categorization Process

- Minimize any unnecessary reliance on S/W or S/W controlled systems for nuclear safety
- Ensure that S/W necessary for nuclear safety is clearly identified, understood and achieved
- Select the S/W Engineering practices which assures the reliability and safety of the S/W
- Categorize S/W with respect to its failure effect on nuclear safety

## S/W Categorization Process - Necessary Definitions

- Safety-Related System A plant system that, upon failure, has the potential to impact the radiological safety of the public or plant personnel due to the operation of the nuclear power plant (NPP).
- Nuclear Safety-Related Functional Requirements those functional requirements which ensure that the system will fulfill its role in achieving acceptable levels of radiological safety with respect to the public and plant personnel
- **Process System** a safety-related plant system whose role is to contribute, directly or indirectly to the **production of electricity**.
- Initiating Event a malfunction of a plant system that would, in the absence of Special Safety System actions, lead to a release of radioactivity which could result in doses exceeding the most restrictive regulatory dose limit for that station.
- Mitigating System a safety-related system that has nuclear safety-related functional requirements to reduce the consequences of an initiating event.

## S/W Categorization Process - Necessary Definitions...continued

- Safety System Significance a classification (into High, Medium or Low) of the plant system in terms of its importance to nuclear safety
- Software Failure Impact the impact of the failure of that S/W with respect to the nuclear safety related functional requirements of the host plant system
- Minimum Performance Requirements the minimum amount of equipment, and the minimum functional and performance characteristics of that equipment, necessary to achieve the plant system performance specified in the safety analysis completed in support of that station operating license.

#### Specification of the S/W Categories

- The Software Category is represented by a *number* from 1 to 4
- Category 1 S/W considered the most important to Nuclear Safety
- <u>S/W Nuclear Safety Category 1</u> is also referred to as *Safety Critical* Software
- Failure of Safety Critical S/W can result in a system with a high safetyrelated reliability requirement not meeting its minimum performance requirements or can result in a serious initiating event (low frequency limit) in a process system.
- Category 4 S/W is to have no importance to Nuclear Safety
- <u>S/W Nuclear Safety Category 2</u> Failure of this S/W can result in a serious process failure, or a degradation in the performance of a mitigating system.
- There is a distinct reduction in safety significance from Category 1 S/W since the consequences of the Category 2 S/W failure can still be mitigated by special safety system action.

<u>S/W Nuclear Safety Category 3</u> - Failure of this S/W does not prevent the affected plant system from meeting its Nuclear Safety-related design intent or the affected plant system has a low safety significance.

#### **Categorization Process Basis**

Fundamental Basis - As the Safety Significance of the S/W decreases, less effort is required to be expended to demonstrate that the S/W meets its requirements.

Risk Based Approach to Nuclear Safety - The risk associated with the failure of a system to perform is a function of the Probability of the failure and the Consequences of the failure (the higher the risk associated with a failure, the higher the assurance must be that the S/W will not contribute to that failure).

Acceptable levels of plant risk are achieved by - Designing the plant to have a low probability of serious process failures, and by providing redundant mitigating systems that minimize the consequences of serious process failures, should they occur.

#### Two Phases for the Categorization Process

- Phase I; Determine the System's Safety Significance
- Phase II; Determine the S/W Failure Impact

#### Two Phases for the Categorization Process

- Phase I; Determine the *System's Safety Significance* This involves identifying the safety significance (as *High*, *Medium* or *Low*) for the plant system of which the S/W to be categorized is a part.
- Safety Significance Determination The safety significance is obtained by determining the system type (safety-related, mitigating, process, etc) and quantifying the systems reliability requirements
- It is also important to note that *more stringent reliability requirements* due to factors other than nuclear safety may be used (i.e. *engineering judgment*, experience, etc.) to justify selecting a *more restrictive* S/W category
- Phase II; Determine the S/W Failure Impact This involves identifying and classifying the worst possible S/W failure modes and effects in terms of impairment of plant safety functions.
- Failure Impact Types The Failure Impact Type is identified as Type I, II or III with Type I representing a failure with the greatest consequences with respect to Nuclear Safety.

Failure Impact Type Analysis - The determination of the failure impact type is based on an analysis of the role of the S/W with respect to the safety-related function of the system and on the independent mitigating provisions within the plant system which can mitigate the consequences of the S/W failure.

#### **Failure Impact Type Considerations**

- Assess all Failure Impacts Within a plant system there can be subsystems that perform multiple functions.
- The Failure Impact Assessment must *identify all possible safety-related impacts* of S/W failure on a plant system.
- For the purposes of categorization, the most severe S/W failure impact type should be used.
- Failure Impact If the worst-case S/W failure is not Type I, then it is possible to reduce the stringency of the S/W category because the role of the S/W within the plant system is less significant from a safety perspective than the role of the overall plant system.

#### **Definition of Plant Safety Significance values for Phase I use**

• Safety & Mitigating Systems Safety Significance

High Significance: Q.LE. 10-3 yr/yr (Q= unavailability req'mt)

Medium Significance: 10-3 .LT. Q .LT. 10-1 yr/yr

Low Significance: Q.GE. 10-1 yr/yr

• Process Systems Safety Significance - Process System Failures

High Significance: f.LE. 10-3 occ/yr (f= event frequency limit)

Medium Significance: 10-3 .LT. f .LE. 10-2 occ/yr

Low Significance: f.GT. 10-2 occ/yr

• Monitoring/Testing Systems Safety Significance

High Significance: Q.LE. 10-3 yr/yr (Q= unavailability req'mt)

Medium Significance: 10-3 .LT. Q .LT. 10-1 yr/yr

Low Significance: Q.GE. 10-1 yr/yr

#### Four Steps to follow for Phase I - Determining Plant Safety Significance

- 1. Identify the Plant System or Systems Involved -Determine which plant systems the S/W or S/W controlled systems are a part of or interact with and determining the role of the S/W.
- 2. Determine the Plant System Type Identify each role for the plant system's nuclear safety functions and determine if it is a special safety, mitigating, process or monitoring/testing system
- 3. Establish a Suitable Plant System Boundary -Selection of the boundary influenced by data availability by using either system unavailability requirements or the initiating event frequency limit
- 4. Determine the Plant System Safety Significance -High, Medium or Low

#### Four Steps for Phase II - Determining S/W Failure Impact Type

- 5. Identify All S/W Failure Modes & Effects Assess the interactions of the relevant sub-systems that comprise the plant system to determine the possible failure impacts of the S/W for all conceivable failure modes.
- Credit S/W and Computer System Design Attributes This is an optional additional step to consider the possibility of S/W and computer system design attributes for preventing or minimizing specific failure modes.
- 6. Determine the limiting S/W Failure Impact Type Apply the classification criteria to determine Type 1-3 Failure Impact Type
- 7. Determine the S/W Category Use the determined the plant system S/W failure Safety Significance (Column data) and the S/W Failure Impact Type (Row Data) to find the S/W Category Matrix intersection value which is the S/W Category value
- 8. Determine the limiting S/W Category This step is necessary when the application involves more than one system or can be classified as more than one type. The most restrictive category should be used.
- Note that S/W categorization *can be Iterative* An initial category may be determined and then further analysis may be initiated in order to resolve any issues which arise during the design process

## The Criteria for S/W Failure Impact for Safety or Mitigating Systems

- Type I The designed nuclear safety functions will not be available or the minimum performance requirements of the plant system will not be met for some or all process system failures.
- Type II The system's functional performance is degraded for some or all process system failures but the minimum performance requirements of the plant system will be met. Or the system's redundancy is reduced such that the probability of not meeting the minimum performance is increased
- Type III The S/W failure has no impact on the nuclear safety functions of the plant system

## The Criteria for S/W Failure Impact Type for Process Systems

- Type I The S/W failure can, in the absence of safety or mitigating system actions, directly or indirectly cause systematic fuel failures or release of radioactivity which could result in doses exceeding the most restrictive regulatory dose limit for the station
- Type II The S/W failure can directly or indirectly raise the temperature of the fuel but not lead to systematic fuel failures. Or the S/W failure leads to an increase in probability of the Type I consequences of systematic fuel failure or releases (probability)
- Type III The S/W failure has no impact on the nuclear safety-related reliability performance of the nuclear safety functions of the plant system

#### The Criteria for S/W Failure Impact Type for Testing Systems

- Type I The S/W failure can cause the designed nuclear safety functions under test not to be available or the minimum performance requirements of the plant system under test not to be met for some or all process system failures
- Type II The S/W failure causes an *inaccurate test result* or *degrades* the functional performance of the system under test or causes a redundancy reduction in the system under test but the minimum performance requirements of the plant system will still be met for all process system failures.
- Type III The S/W failure has no impact on the test or on the safety-related performance of the system under test.

## S/W Categorization tabled as a function of Safety Significance & Failure Impact Type

System Safety	Impact Type I	Impact Type II	Impact Type III
Significance			
High	Cat. 1	Cat. 2	Cat. 4
Medium	Cat. 2	Cat. 3	Cat. 4
Low	Cat. 3	Cat. 3	Cat. 4

## S/W Categorization 1-4 Process Summary

- Safety Critical S/W The standard for Safety Critical S/W will only be applied to Special Safety Systems and to Process Systems for which the initiating event frequency is less than 10-3 occ/yr.
- Reduction in S/W Rigour from Category 1 to 2 Occurs: If the system Safety Significance decreases from High to Medium while the S/W Failure Impact remains Type I, or if the Safety Significance remains High but the Failure Impact Type is reduced from Type I to Type II.
- Category III Application If the system Safety Significance is Low and the S/W Failure Impact Type is I or the system has a Medium or Low Safety Significance and the Failure Impact Type is II.
- Category IV Application: If the S/W Failure Impact Type is III (no Safety-Related Impact) the S/W is assessed as Category IV.

## Lecture Summary - CANDU NPP S/W Categorization Methodology

- Purpose of the S/W Categorization Process
- Necessary Definitions
- Specification of the S/W Categories
- Categorization Process Basis
- Determining Plant System Safety Significance
- Determining S/W Failure Impact Type
- Final S/W Category Determination
- S/W Categorization 1-4 Summary